



| | | | |
|----------------|---------------------|---------------------|--|
| PT6A-41 | | SN PCE-80827 | |
| Value | Times/Cycles | | |
| TTSN | 2,282 | | |
| TCSN | 1,598 | | |
| TSO | 0 | | |
| CSO | 0 | | |
| TSHSI | 0 | | |

OH by Midwest Turbine Services-November 14, 2023

HSI by Midwest Turbine Services-November 14, 2023

POST SB3360

| Part Number | Description | Serial Number | Total Cycles | Cycle Limit | Cycles Remaining |
|-------------|------------------|---------------|--------------|-------------|------------------|
| 3021911 | Compressor Hub | 3A453 | 1,598 | 20,000 | 18,402 |
| 3134863 | #2 Comp Disc | A000C3X8 | 1,057 | 20,000 | 18,943 |
| 3134864 | #3 Comp Disc | A00057FB1 | 0 | 20,000 | 20,000 |
| 3017643 | Impeller | 1A616 | 1,598 | 20,000 | 18,402 |
| 3049291-01 | CT Disc | A000CDE9 | 2,575 | 10,000 | 7,425 |
| 3029312 | #1 PT Disc | 9Y514 | 7,883 | 30,000 | 22,117 |
| 3029313 | #2 PT Disc | 9Y458 | 7,883 | 30,000 | 22,117 |
| E3123131-02 | CT Blades (58ea) | N/A | TSN: 0 | | |

| Part Number | Description | Serial Number | TSO |
|---------------|------------------|---------------|---------------|
| 8210-007-01 | Prop Governor | 16336753 | 0 |
| 3244707-6 | Torque Limiter | A24544 | 0 |
| 025323-300-03 | Fuel Pump | 7619 | 0 |
| 3244755-22 | FCU | A77794 | 0 |
| 10585K | Oil/Fuel Heater | WA6430 | 0 |
| 3123122-01 | HP Bleed Valve | B1537 | 0 |
| 3100923-02 | LP Bleed Valve | 6E128 | 0 |
| 3019906 | Flow Divider | 2824 | 0 |
| Not Installed | Ignition Exciter | Not Installed | Not Installed |

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.