



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

| PT6A-27/28 SN PCE-50565 | | |
|-------------------------|--------------|--|
| Value | Times/Cycles | |
| TTSN | 9,659 | |
| TCSN | 9,489 | |
| TSO | 0 | |
| CSO | 0 | |
| TSHSI | 0 | |

OH in progress

HSI in progress

Build to Spec with estimated 45 day lead time

| Part Number | Description | Serial Number | Total Cycles | Cycle Limit | Cycles Remaining |
|-------------|--------------|---------------|--------------|-------------|------------------|
| 3013111 | Rear Hub | 6538 | 9,489 | 19,000 | 9,511 |
| 3013712 | #2 Comp Disc | 8710 | 9,489 | 24,000 | 14,511 |
| 3011713 | #3 Comp Disc | 7401 | 9,489 | 25,000 | 15,511 |
| 3013176 | Impeller | A4414 | 9,489 | 19,000 | 9,511 |
| 3013411 | CT Disc | A9490 | 9,489 | 16,000 | 6,511 |
| 3022412 | PT Disc | A0167 | 10,000 | 20,000 | 10,000 |

| Part Number | Description | Serial Number | TSO |
|---------------|------------------|---------------|---------------|
| 8210-002 | Prop Governor | 1994317 | 0 |
| 025423-101-02 | Fuel Pump | 1936 | 0 |
| 2624440-7-6 | FCU | A59762 | 0 |
| 25234-2 | Start Control | 7323 | 0 |
| 10552E | Oil/Fuel Heater | 1860 | 0 |
| 3100829-03 | Comp Bleed Valve | AAHX006266 | 0 |
| Not Installed | Ignition Exciter | Not Installed | Not Installed |
| 25234-2 | Start Control | 7323 | 0 |

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

March 4, 2026