



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

PT6A-34 SN PCE-40394	
Value	Times/Cycles
TTSN	32,915
TCSN	35,565
TSO	0
CSO	0
TSHSI	0

OH by BV Aviation- January 2026

HSI by BV Aviation- January 2026

BS1273

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	1B222	9,544	19,000	9,456
3013712	#2 Comp Disc	9A772	9,544	24,000	14,456
3011713	#3 Comp Disc	8A938	9,544	25,000	15,456
3013176	Impeller	2A402	9,544	19,000	9,456
3013411	CT Disc	7A736	9,544	16,000	6,456
3022412	#1 PT Disc	5A552	9,544	20,000	10,456
E3045741-01	CT Blades (58ea)		New		

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
442569-1	FCU	C76334	0
025323-101-03	Fuel Pump	R1470	0
3019906	Flow Divider	13613	0
3100829-03	Comp Bleed Valve	1A368	0
Not Installed	Ignition Exciter	Not Installed	Not Installed
10552E	Oil/Fuel Heater	4051	0

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

February 4, 2026