



PT6A-28 SN PCE-51052	
Value	Times/Cycles
TTSN	11,260.2
TCSN	8,970
TSO	0
CSO	0
TSHSI	0

OH by Turbine Standard- July 2023

HSI by Turbine Standard- July 2023

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	A0262	8,970	19,000	10,030
3013712	#2 Comp Disc	A0551	8,970	24,000	15,030
3011713	#3 Comp Disc	B1484	8,970	25,000	16,030
3013176	Impeller	A8863	8,970	19,000	10,030
3013411	CT Disc	A8063	8,970	16,000	7,030
3022412	PT Disc	A2575	8,970	20,000	11,030

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
TBD	Fuel Pump	7508D	0
2524440-7-6	FCU	A7069	0
10552E	Oil/Fuel Heater	4859	0
3100829-03	Bleed Valve	A5883	0
3019109	Start Control	14157	0
Not Installed	Ignition Exciter	Not Installed	Not Installed

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

July 31, 2023