

Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

| PT6A-61 | SN PCE-HA0167 | | | | |
|---------|---------------|--|--|--|--|
| Value | Times/Cycles | | | | |
| TTSN | 3,402.2 | | | | |
| TCSN | 2,185 | | | | |
| TSO | N/A | | | | |
| CSO | N/A | | | | |
| TSHSI | 1586.7 | | | | |

HSI-March 24, 2016 BS1236 King Air Configured

| Part Number | Description | Serial Number | Total Cycles | Cycle Limit | Cycles Remaining |
|-------------|--------------|---------------|--------------|-------------|------------------|
| 3041271 | Rear Hub | EAAC000R225 | 2,185 | 15,000 | 12,815 |
| 3034312 | #2 Comp Disc | A0035F1X | 2,185 | 20,000 | 17,815 |
| 3034313 | #3 Comp Disc | A0035LEE | 2,185 | 20,000 | 17,815 |
| 3036793 | Impeller | EAAC000R783 | 2,185 | 24,000 | 21,815 |
| 3040311 | CT Disc | YUAA011A012 | 2,185 | 15,000 | 12,815 |
| 3029312 | #1 PT Disc | A00367RW | 2,185 | 30,000 | 27,815 |
| 3029313 | #2 PT Disc | YUAA011A215 | 2,185 | 30,000 | 27,815 |

| Part Number | Description | Serial Number | TSN |
|-------------|------------------|---------------|---------|
| 8210-024-01 | Prop Governor | 17948096 | 3,402.2 |
| 8061-345 | FCU | 17943773 | 3,402.2 |
| 3019906 | Flow Divider | 9959559150 | 3,402.2 |
| 10585K | Fuel Heater | WA44529 | 3,402.2 |
| 852601-5 | Fuel Pump | 011655 | 3,402.2 |
| 3244707-8 | Torque Limiter | D13525 | 3,402.2 |
| 3117032-01 | Comp Bleed Valve | AHX2900211 | 3,402.2 |
| CH92108-1 | Ignition Exciter | 121104 | 3,402.2 |

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS.

THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.