



Pre-buy Spec Sheet

Data subject to change prior to finalization.

| PT6A-114A SN PCE-PC0524 | |
|-------------------------|--------------|
| Value | Times/Cycles |
| TTSN | 14,915 |
| TCSN | 19,690 |
| TSO | 0 |
| CSO | 0 |
| TSHSI | 0 |

OH- January 2025

HSI -January 2025

POST SB1669

| Part Number | Description | Serial Number | Total Cycles | Cycle Limit | Cycles Remaining |
|-------------|--------------|---------------|--------------|-------------|------------------|
| 3013111 | Rear Hub | 3H699 | 13,229 | 19,000 | 5,771 |
| 3013712 | #2 Comp Disc | 2A902 | 13,349 | 24,000 | 10,651 |
| 3011713 | #3 Comp Disc | A0001E3H | 6,517 | 25,000 | 18,483 |
| 3027798 | Impeller | EAAB000T610 | 9,892 | 19,000 | 9,108 |
| 3013411 | CT Disc | A0015NE3 | 10,585 | 16,000 | 5,415 |
| 3026812 | PT Disc | 5R212 | 3,629 | 20,000 | 16,371 |
| 3072791-01 | CT Blades | | TSN: 3,508 | | |
| 3072791-01 | CT Blades | | TSN: 0 | | |

| Part Number | Description | Serial Number | TSO |
|---------------|----------------------------|---------------|---------------|
| 8210-002-01 | Prop Governor | 14400843 | 738 |
| 702801-5 | Fuel Pump | 001269 | 381 |
| 3244897-4 | FCU | C65943 | 0 |
| 3019906 | Start Control/Flow Divider | 16816 | 0 |
| 10552E | Oil/Fuel Heater | 4772 | 381 |
| Not Installed | Ignition Exciter | Not Installed | Not Installed |
| 540-1407-4 | Comp Bleed Valve | GA1212 | 0 |

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

January 30, 2025