



**Pre-buy Spec Sheet**

**Data subject to change prior to finalization.**

PT6A-114A SN PCE-PC1409	
Value	Times/Cycles
TTSN	3,554
TCSN	1,261
TSO	0
CSO	0
TSHSI	0

**Lead time 75 days**

**OH-Estimated for March 2025**

**HSI-Estimated for March 2025**

**POST SB1749**

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	RWA72A305	1,261	19,000	17,739
3013712	#2 Comp Disc	A0026T1A	1,261	24,000	22,739
3011713	#3 Comp Disc	A0026R7H	1,261	25,000	23,739
3027798	Impeller	EAAB000B133	1,261	19,000	17,739
3013411	CT Disc	A0026WSC	1,261	16,000	14,739
3026812	PT Disc	A0026MED	1,261	20,000	18,739
3079351-01	CT Blades (58 ea)		TSN: 1,799	5,000 Hrs	3,201 Hrs

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
3034792	Fuel Pump	001602	0
3244789-3	FCU	B10642	0
3019906	Flow Divider	9959513066	0
10552E	Oil/Fuel Heater	WA29596	0
Not Installed	Ignition Exciter	Not Installed	Not Installed
540-1407-4	Comp Bleed Valve	5454	0

**Contact Info:**

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS.

THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

January 10, 2025