



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

PT6A-42 SN PCE-PJ1190	
Value	Times/Cycles
TTSN	7,306
TCSN	6,709
TSO	1,333
CSO	1,150
TSHSI	0

POST SB3360

Prop-strike repair in process-30 day lead time

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3053921-01	Compressor Hub	EAAB000B722	6,709	20,000	13,291
3134863	#2 Comp Disc	A0056W4T	1,150	20,000	18,850
3023113	#3 Comp Disc	A0022EEF8	6,709	20,000	13,291
3036793	Impeller	EAAB000N456	6,709	24,000	17,291
3049291-01	CT Disc	A0029FCH	6,709	10,000	3,291
3029312	#1 PT Disc	A002F4FW	6,709	30,000	23,291
3029313	#2 PT Disc	A002F372	6,709	30,000	23,291

Part Number	Description	Serial Number	TSO
3074159-01	Prop Governor	16263289	1,333
3033808	Fuel Pump	9261	1,333
3049644-01	FCU	D20538	1,333
3057249-01	Oil/Fuel Heater	WA34605	1,333
3123122-01	Comp Bleed Valve	AHX012448	1,333
3123123-01	Comp Bleed Valve	AHX012638	1,333
3244801-1	Flow Divider	A00377	1,333

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.