



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

PT6A-42 SN PCE-PJ1191	
Value	Times/Cycles
TTSN	7,358
TCSN	6,738
TSO	1,781
CSO	1,566
TSHSI	0

POST SB3360

Prop-strike repair in process-30 day lead time

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3053921-01	Compressor Hub	66B776	6,738	20,000	13,262
3023112	#2 Comp Disc	A002F4	6,738	20,000	13,262
3023113	#3 Comp Disc	A002F370	6,738	20,000	13,262
3036793	Impeller	TXA1B5778	6,738	24,000	17,262
3049291-01	CT Disc	A002F53D	6,738	10,000	3,262
3029312	#1 PT Disc	A002F4FY	6,738	30,000	23,262
3029313	#2 PT Disc	A002F370	6,738	30,000	23,262

Part Number	Description	Serial Number	TSO
8210-024-01	Prop Governor	1818590	1,781
3033808	Fuel Pump	9145	1,781
3049644-01	FCU	D20535	1,781
10585K	Oil/Fuel Heater	WA64824	1,781
3123122-01	Comp Bleed Valve	AHX012451	1,781
3123123-01	Comp Bleed Valve	AHX012501	1,781
3244801-1	Flow Divider	8077	1,781

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.