



**Pre-buy Spec Sheet**

Data and quoted prices are subject to change prior to finalization.

PT6A-34 SN PCE-RB0684	
Value	Times/Cycles
TTSN	7,998.6
TCSN	9,101
TSO	0
CSO	0
TSHSI	0

**BS1273**

**OH in progress**

**HSI in progress**

**Lead time 60 days**

Part Number	Description	Serial Number	Cycle Limit	Total Cycles	Cycles Remaining
3013111	Rear Hub	RWA78D620	9,101	19,000	9,899
3013712	#2 Comp Disc	A0038K9F	9,101	24,000	14,899
3011713	#3 Comp Disc	A0038K8N	9,101	25,000	15,899
3032249	Impeller	EAAC000437	9,101	19,000	9,899
3013411	CT Disc	YUAA011A789	9,101	16,000	6,899
3026812	#1 PT Disc	YUAA012A161	9,101	20,000	10,899

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
3244834	FCU	TBD	0
025323-101	Fuel Pump	TBD	0
3019906	Flow Divider	TBD	0
3100329-03	Comp Bleed Valve	TBD	0
Not Installed	Ignition Exciter	Not Installed	Not Installed
10552E	Oil/Fuel Heater	TBD	0

**Contact Info:**

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

April 11, 2025