



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

PT6A-34 SN PCE-RB0685	
Value	Times/Cycles
TTSN	7,998.6
TCSN	9,049
TSO	0
CSO	0
TSHSI	0

BS1273

OH in progress

HSI in progress

Lead time 60 days

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	RWA81D536	9,049	19,000	9,951
3013712	#2 Comp Disc	A00393RE	9,049	24,000	14,951
3011713	#3 Comp Disc	A00393PP	9,049	25,000	15,951
3013176	Impeller	EAAC000Y410	9,049	19,000	9,951
3013411	CT Disc	YUAA011A746	9,049	16,000	6,951
3026812	#1 PT Disc	YUAA012A108	9,049	20,000	10,951

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
25234-2	Start Control	TBD	0
3244834	FCU	TBD	0
3034794	Fuel Pump	TBD	0
TBD	Flow Divider	TBD	TBD
3075033-01	Comp Bleed Valve	TBD	0
Not Installed	Ignition Exciter	Not Installed	Not Installed
10552E	Oil/Fuel Heater	TBD	0

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

April 11, 2025