



**Pre-buy Spec Sheet**

**Data and quoted prices are subject to change prior to finalization.**

PT6A-34 SN PCE-RB1188	
Value	Times/Cycles
TTSN	560.7
TCSN	249
TSO	N/A
CSO	N/A
TSHSI	N/A

**BS1218 Kodiak**

**Lead time 8 weeks due to prop strike repair.**

**Details subject to change.**

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	RWA50F790	249	19,000	18,751
3013712	#2 Comp Disc	A004BM8P	249	24,000	23,751
3011713	#3 Comp Disc	A004BDEE	249	25,000	24,751
3013176	Impeller	CRAZAFFI114	283	19,000	18,717
3013411	CT Disc	CRAZAFFU293	249	16,000	15,751
3026812	#1 PT Disc	YUAB001L969	283	20,000	19,717

Part Number	Description	Serial Number	TSN/TSO
3074154-01	Prop Governor	21515058	560.7
3122696-04	FCU	F26490	560.7
3071057-01	Fuel Pump	000296	560.7
3019906	Flow Divider & Dump Valve	L1954	560.7
3049038-03	Comp Bleed Valve	9350	560.7
3035889	Ignition Exciter	NNA18420003	560.7
3032710	Oil/Fuel Heater	WA58355	560.7

**Contact Info:**

Cell Phone: 254-242-6840

Email: [sales@dunkinaviationsolutions.com](mailto:sales@dunkinaviationsolutions.com)

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS.

THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

April 11, 2025