



Pre-buy Spec Sheet

Data and quoted prices are subject to change prior to finalization.

PT6A-21 SN PCE-25838		
Value	Times/Cycles	
TTSN	3,593	
TCSN	3,714	
TSO	0	
CSO	0	
TSHSI	0	

OH by Consolidated Turbine Specialist, LLC- June 16, 2025

HSI by Consolidated Turbine Specialist, LLC- June 16, 2025

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	8P851	13,503	19,000	5,497
3013712	#2 Comp Disc	17A169	17,855	24,000	6,145
3011713	#3 Comp Disc	99A824	19,139	25,000	5,861
3013176	Impeller	6D752	13,423	19,000	5,577
3013411	CT Disc	6L372	7,413	16,000	8,587
3022412	#1 PT Disc	24B8801	14,583	20,000	5,417

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
3244745-3	FCU	C17075	0
26035-1	Flow Divider	0502	0
386101-5	Fuel Pump	1326	531
10552E	Fuel/Oil Heater	WA4475	0
3100829-03	Bleed Valve	14A329	0
Not Installed	Ignition Exciter	Not Installed	Not Installed

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS.
THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

August 12,2025