



PT6A-28		SN PCE-51050	
Value	Times/Cycles		
TTSN	11,353.2		
TCSN	9,001		
TSO	0		
CSO	0		
TSHSI	0		

**OH by Turbine Standard- August 9, 2023**

**HSI by Turbine Standard- August 9, 2023**

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Rear Hub	A1698	9,001	19,000	9,999
3134862	#2 Comp Disc	A2520	9,001	24,000	14,999
3134861	#3 Comp Disc	8970	9,001	25,000	15,999
3013176	Impeller	A8827	9,001	19,000	9,999
3013411	CT Disc	6402	8,618	16,000	7,382
3022412	PT Disc	A2533	9,001	20,000	10,999

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
025323-101-03	Fuel Pump	11634	0
2524440-7-6	FCU	A25319	0
10552E	Oil/Fuel Heater	1118	0
3100829-03	Bleed Valve	A8852	0
25234-5	Start Control	7937	0
Not Installed	Ignition Exciter	Not Installed	Not Installed

**Contact Info:**

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

**ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.**

August 24, 2023