



Pre-buy Spec Sheet

Data subject to change prior to finalization.

PT6A-42 SN PCE-93229/93229-100		
Value	GG Times/Cycles	PS Times/Cycles
TTSN	20,927	20,702.9
TCSN	15,310	15,134
TSO	0	0
CSO	0	0
TSHSI	0	0

POST SB3360

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3041501	Compressor Hub	11B932	10,999	30,000	19,001
3023112	#2 Comp Disc	TBD	10,126	20,000	9,874
3023113	#3 Comp Disc	TBD	11,447	20,000	8,553
3017463	Impeller	4A520	7,266	20,000	12,734
3049291-01	CT Disc	A000BLX7	5,901	10,000	4,099
3029312	#1 PT Disc	18B532	14,234	30,000	15,766
3029313	#2 PT Disc	4W365	14,143	30,000	15,857

Part Number	Description	Serial Number	TSO
Not Installed	Prop Governor	Not Installed	Not Installed
3244707-7	Torque Limiter	C12544	TBD
399701-5	Fuel Pump	3750	0
3244768-14	FCU	C20941	0
10585K	Oil/Fuel Heater	16194	0
Not Installed	Ignition Exciter	Not Installed	Not Installed
3100922-05	HP Bleed Valve	31499	0
3123043-01	LP Bleed Valve	47A947	0
3036640	Flow Divider	1573	0

Contact Info:

Cell Phone- 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.

April 9, 2024