



**Pre-buy Spec Sheet**

**Data and quoted prices are subject to change prior to finalization.**

PT6A-135A SN PCE-PZ0552	
Value	Times/Cycles
TTSN	2,860
TCSN	2,877
TSO	174
CSO	137
TSHSI	174

**OH by Southwest Airmotive-July 2022**

**HSI by Southwest Airmotive-July 2022**

Part Number	Description	Serial Number	Total Cycles	Cycle Limit	Cycles Remaining
3013111	Compressor Hub	RWA83A808	2,877	19,000	16,123
3013712	#2 Comp Disc	A0028362	2,877	24,000	21,123
3011713	#3 Comp Disc	A00285Y3	2,877	25,000	22,123
3027798	Impeller	EAAA000L276	3,115	19,000	15,885
3024211	CT Disc	A00285W1	2,877	16,000	13,123
3022312	PT Disc	A002838A	2,877	30,000	27,123

Part Number	Description	Serial Number	TSO
8210-025-01	Prop Governor	11951795	174
025323-150	Fuel Pump	801	174
4138013-1	FCU	C80419	174
10552E	Fuel/Oil Heater	4675	174
3100829-03	Comp Bleed Valve	6C757	174
3019906	Flow Divider	2290	174
Not Installed	Ignition Exciter	Not Installed	Not Installed

**Contact Info:**

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

**ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSORIES.**

February 10, 2026